

# Thermometer set, Elma 711+101+116

## Set of thermometer with surface and air sensor

EAN 5703317550132 / EL-NR 6398189019

Set of Elma 711 Thermometer Type 101 surface sensor Type 116 Air sensor Elma 711 is our well known, rugged thermometer with rubber protection and table stand, suitable for all branches. Furthermore 99 values can be saved in the memory, easy to scroll through, using the arrow keys. Elma 711 is the simplest in the 71x series, very easy to use and compatible with type K thermocouples, the most used type in industrial applications. Elma 711 is designed ergonomically, to use all functions with one hand and the large display is easy readable. The instrument offers max/min hold, selectable units °C/°F and resolution of 0.1 or 1 °C/°F. Elma 711 is delivered ready to use incl. rubber protection, batteries, TP01 wire sensor (-50°C...250°C) and manual. Please find a selection of sensors in the "Accessories" tab.



### Technical data:

Range:	-50..1350°C
Accuracy:	±0,1% RDG ± 1°C
Range sensor type 101:	-50...450°C
Accuracy sensor type 101:	±2,5° or ±0,75% RDG (greatest)
Range sensor type 116:	-50...600°C
Accuracy sensor type 116:	±1.5° or ±0,4% RDG (greatest)
Resolution:	0.1 °C
Sensor type:	Thermocouple type K
Display:	3 1/2 digit LCD
Max display:	1999
Working temperature:	0...40°C
Working humidity:	Max. 80 %RH
Batteries:	6 pcs. of LR03 AAA 1.5V (Incl.)
Dimensions:	135x72x31mm
Weight:	235g

### Related products

EAN	EL-NR	Product
5703317440273	6398586010	TP01 wire sensor
5703317550033	6398157863	Air temperature sensor type 116
5703317550057	6398157915	109 Clamp temperature sensor
5703317550071	6398157931	106 Penetration probe
5703317550088	6398157944	104 Universal probe
5703317550095	6398157957	Surface temperature sensor type 101
5703317550125	6398157999	110 Surface probe
5706445140169	6398167251	Universal instrument bag Elma Maxi - Professional storage

